

2018 Ram 1500/2500/3500 Security Bypass Install



All 2018 FCA vehicles are built with an SGW Security Gateway Module that prevents access to the vehicle from the OBD2 port by anything but the dealer diagnostic tools.

• 2018 Ram 1500-3500

Installation

Step 1: Remove the 2 screws under the top rubber mat above the radio

Step 2: Remove the 1 screw behind the rubber mat in the cubby above the 110v outlet if equipped





Step 3: Gently Pull from the edges the radio bezel away from the instrument panel.



Step 4: Remove the four fasteners securing the Radio to the instrument panel



Step 5: Remove the radio from the instrument panel.

Step 6: Remove the 3 bolts holding the Security Gateway bracket to the instrument panel



Step 7: Unplug connectors going into Security Gateway Module (1)



Step 8: Plug in Security Bypass Block into Existing Connectors and tuck up inside.

Step 9: Reinstall Radio and Dash Bezel.

DISCLAIMER:

Bypass DOES need to be removed prior to bringing vehicle into service or else dealer tools will not work.

Z Automotive cannot be held responsible misuse or consequential damages. If you are in doubt, email techsupport@zautotech.com. Please be aware that modifying your vehicle in any way can affect your vehicle's warranty, longevity, handling, etc. Please use with caution, and AT YOUR OWN RISK.